




Fig 26





Fip 3

Reel Barge






Fig 5




Fig (






FIG 7










FIG 10









FIG 14






FIG 16






FIG 18








FIG 21





FIG 22







Fig 2

Fig. 25







Fig. 2#






Fig 28




Fig 2





Fig 3







Fig 32



**Fig** 33





Fig 34

System	Pre-Repair Burial Status	Date of Fault	Water Seabed Type Type of Eault Double	Type of Eart	Water	ř	
		,	246	ו אם מו ו מתו	r Deptil	Type of Armour Repair Ship	Repair Ship
CANUS 1	Surface Laid	1-Mari-98	Sand	Dredging	65 ft	Double Armor	Sir Eric Sharp .
TAT 7	Surface Lald	. 18-Apr-86	Sand	Anchor	90 ft	Unknown	Mercury
TAT 7	· Surface Laid	. 10-Aug-89	. Sand	. Fishing	175 ft	Ughtweight	C.S. Alert
TAT 7	Unknown	9-Aug-93	Unknown	Repeater	160 ft	Unknown	Global Mariner
TAT 8	Postiay Burled	10-Äug-93	Unknown	Unknown	90 ft	LWP	Global Mariner

F16 3



**Fig** 36




FIG 37




FIG 38

FIG 39





Fig. 40



F19. 4









Fig. 42


















Figure 49

Figure 50



. ,

Fig. 51




Fig. 52

